



**3 1/2" Gauge "Hielan Lassie".** This is a well made locomotive in need of some TLC. A Combustion Chamber tube has been damaged and to repair two holes were cut in the boiler outer. Unfortunately the patch has been attached to the outside of the boiler and sealed with a hard grade of tin solder. Our Club boiler inspectors will not pass this as suitable. A smart engineer may well be able to remove and do a suitable repair. This is a three cylinder engine and all the motion and rolling gear appear to be in very good order. The cladding sheet has been misplaced. And as can be seen the engine would require repainting.

